

Photo 13 – After Remediation Side Strip




Photo 14 – After Remediation Front Yard







Photo 15 – After Remediation Front Yard & Garden



Photo 16 – After Remediation Back Yard & Under Deck





	NON-RESPONSIVE	CACEGO TA BRABERTY	
Name (please			
Daytime Phor			
Evening Phon			
Email:			
Address of Pr			

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq*.

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact-me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

We

PROJECT No.: 39826-19 DESIGNED BY:\_ CRA PROJECT NAME: \_ **CONESTOGA-ROVERS & ASSOCIATES** CHECKED BY: 602 DATE: 4/6/16 PAGE \_ OF 5. Keylote & G. 152 Gorage Bucks S. A.L. 心情 4.4 x 66 · 50:1 0 2.2+19 Q spil -5. 100400-900-900 | 10001 0 Sider of House is Gorge Story 60 DOOR noor 20 Perticulate well readings were below there Level

Property Inst	nection Form – Pilsen OU2	Area
Parce Lawn A		_
Flowers/Plants:	WYes □ No All can go	
Soil (grade) next to structure:		nl -002.07
Shrubbery:	∑Yes □ No <u>Centuryard r</u> □ Yes □ No	ull alt gravel
Trees:	MYes No Wolft Trew	ull sty
Sidewalks	Restoration Plan	
Sidewalk:	☐ Yes ☐ No	
Tree Roots:	Yayes No Violet Tree	
Sections Missing:	V☐ Yes ☐ No	
Other:	M Yes No Ronweter go	and will get gravel
Signatures		
ONSIVE		Patrick / 1
vario or forme owner.	Signature :	Date /
- Han Navemo	Olman Voran	me 06/16/12
GHD	Signature	Date
-RESPONSIVE		P/23/17 Date
- Wan Navano	Clana Can	08/23/12
GHD	Signature	Date

NON-RESP



# Structure Current Address:

Property wher mentioned two buried cats

#### **Sketch of Property**






Photo 1 - Before Remediation Back Yard



Photo 2 – Before Remediation Back Yard (2)







Photo 3 - During Remediation Back Yard



Photo 4 – During Remediation Back Yard (2)







Photo 5 - After Remediation Back Yard



Photo 6 – After Remediation Back Yard (3)







Photo 7 – After Remediation Back Yard (2)





NOI	N-RESPONSIVE CONCERNS FOR A CORRESPONDED TO DE OPERATIVO
Name (plea	
Daytime Ph	
Evening Ph	
Email:	
Address of	
Environmenta	fficers, employees, contractors, and authorized representatives of the United States I Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and used access to the property described above to perform the following response actions:
(1) (2)	Collecting samples, surface and subsurface, including but not limited to soil and air; The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
(3) (4)	Removing contaminated soil and related activities; Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
(5)	Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.
	hese possible actions are being undertaken pursuant to the response authorities under the ve Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. et seq.
knowledge of kind. I unders of any investi	Itten permission voluntarily, on behalf of myself and all other co-owners of the Property, with my right to revoke my voluntary consent at any time, and without threats or promises of any stand that EPA, H. Kramer, or their authorized representatives will contact me before the start gation or remedial activities on my property, and I will notify any tenants in my property of stigation or remedial activities.
This documer	nt should be signed only by the legal owner of the property described above.

Owner Signature

Owner Name (p

Owner's Address (if different from the Address listed above): \_\_\_\_\_\_\_



Structure


NON-RESPONSIVE

Current Address:

Description

All plants & flavors will be removed by projectly owner

**Sketch of Property** 





Parcel Landscape Area			Current Address:
Lawn Area			Restoration Plan
Flowers/Plants:	Yes	☐ No	Removed by owner
Soil (grade) next to structure:	☐ Yes	☐ No	- See Property Sketch
Shrubbery:	☐ Yes	☐ No	
Trees:	Yes	□ No	
Sidewalks			Restoration Plan
Sidewalk:	☐ Yes	□ No	
Tree Roots:	☐ Yes	□ No	
Sections Missing:	☐ Yes	□ No	
Other:	Yes	□ No	Front Garden requirer no-further action. Soil below threshold.
ON-RESPONSIVE			8/29/201 ate 08/29/17
Han Navano	Signat	ture	Date Date
ON-RESPONSIVE			
			$\frac{2}{18}$ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
- Van Navarro	U	are	
GHD'	Signat	ture	Date



Structure



Current Address:

Description

All plants & flavors will be removed by projectly owner

#### **Sketch of Property**






Photo 1 – Before Remediation Back Yard




Photo 2 – Before Remediation Back Yard & Garden







Photo 3 – Before Remediation Back Yard & Garden (2)



Photo 4 – Front Garden Resample







Photo 5 - Front Garden Resample (2)



Photo 6 – During Remediation Side Strip







Photo 7 – During Remediation Back Yard & Garden



Photo 8 – During Remediation Back Yard & Garden (3)










Photo 9 – During Remediation Back Yard & Garden (2)




Photo 10 – After Remediation Side Strip








Photo 11 – After Remediation Back Yard & Garden




Photo 12 - After Remediation Back Yard & Garden (2)







NON-RESPONSIVE
Name (pleas
Daytime Pho
Evening Pho
Email:
Address of P
I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:
<ol> <li>Collecting samples, surface and subsurface, including but not limited to soil and air;         The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;     </li> <li>Removing contaminated soil and related activities;</li> <li>Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and</li> <li>Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.</li> </ol>
I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 <i>et seq</i> .
I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any cind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start on any investigation or remedial activities on my property, and I will notify any tenants in my property of uny such investigation or remedial activities.
This document should be signed only by the legal owner of the property described above
NON-RESPONSIVE  Dwner Signature:  Dwner Name (prin
wner's Address (if different from the Address listed above):



Structure


NON-RESPONSIVE

rrent Address:

Description

ONE FLOWER REMOVED (COMP. - \$30)

#### **Sketch of Property**





NON-RESPONSIVE

Parcel Landscape Are	DI .	Current Addres
Lawn Area		Restoration Plan
Flowers/Plants:	Yes 🗆 No	PinK/Lilia Flower (Back) - taken at (8)
Soil (grade) next to structure:	☐ Yes ☐ No	
Shrubbery:	Yes No	3 rose bushes staying
Trees:	Yes 🗆 N	2 bother appront staying
Sidewalks		Restoration Plan
Sidewalk:	☐ Yes ☐ N	0
Tree Roots:	Yes N	work around fre routs
Sections Missing:	☐ Yes ☐ N	0
Other:	☐ Yes ☐ N	See properly sketch for oldail.
Van Navarro	Signature	1 Carrer 00/10/17 Date
OHD	Olghature	Date
RESPONSIVE		8/31/17 Date
RESPONSIVE  Tran Navarro	( na	8/31/17 Date 08/31/17



Structure

rrent Address:

Description

ONE FLOWER REMOVED (COMP. - \$30)

#### **Sketch of Property**






Photo 1 – Before Remediation Front Yard & Garden –
Photo Taken by EPA START 05/02/13



Photo 2 – Before Remediation Front Yard – Photo Taken by EPA START 05/02/13









Photo 3 – Before Remediation Back Yard & Garden – Photo Taken by EPA START 05/02/13



Photo 4 – During Remediation Front Yard







Photo 5 – During Remediation Front Yards & Garden



Photo 6 - During Remediation Back Yard







Photo 7 – During Remediation Back Yard & Garden




Photo 8 – After Remediation Front Yard







Photo 9 – After Remediation Front Yard & Garden




Photo 10 – After Remediation Back Yard







Photo 11 – After Remediation Back Yard & Garden



Photo 12 – After Remediation Back Yard & Garden (2)





CONSENTENTO DA DA EL ACCESO A LA DOODIEDAD
Nombre (en letra d
Teléfono durante e
Teléfono después
Email:
Dirección complet
Doy mi consentimiento a los funcionarios, empleados, confratistas y representantes autorizados de la Agencia de Protección Ambiental de los Estados Unidos (EPA) y / o de H. Kramer & Company (H. Kramer) para que entren y tengan acceso continuo a la propiedad indicada arriba para realizar las siguientes acciones de respuesta:
(1) Recolección de muestras de la superficie y bajo la superficie incluyendo – pero sin limitarse – a la
<ul> <li>tierra y al aire;</li> <li>(2) Documentación de las observaciones científicas y de ingeniería incluyendo – pero sin limitarse – a tomar notas, fotografías y estudios topográficos;</li> <li>(3) Eliminación de tierra contaminada y actividades relacionadas;</li> </ul>
(4) Cumplimiento con las medidas de restauración una vez que se haya removido la tierra contaminada incluyendo el suministro de tierra impoluta por la tierra removida, el suministro de césped para las áreas previamente cubiertas de hierba, la restauración limitada del jardín, la sustitución de grava, el reparo de posibles daños o por pérdida de propiedad como resultado directo del muestreo, la remoción, y las actividades de restauración; y
(5) Otras acciones que sean necesarias para proteger la salud humana y el medio ambiente según determine el coordinador de acciones en terreno de la EPA.
Entiendo que estas posibles acciones se llevan a cabo de acuerdo con las autoridades de respuesta según la Ley de Responsabilidad, Compensación y Recuperación Ambiental de 1980, según enmendada, 42 USC Sección 9601 et seq.
Yo doy este permiso escrito voluntariamente, en nombre mío y de todos los otros dueños de la propiedad, con el conocimiento de mi derecho a revocar mi consentimiento voluntario en cualquier momento, y sin ningún tipo de amenaza o promesa. Entiendo que la EPA, H. Kramer, o sus representantes autorizados se pondrán en contacto conmigo antes del inicio de cualquier investigación o actividad de restauración en mi propiedad, y voy a notificar a todo inquilino en mi propiedad de cualquier investigación o actividad de restauración.
Este documento de NON-RESPONSIVE
Firma del propietar
Nombre del propiet

Dirección completa del dueño (si es diferente a la dirección que aparece arriba):

PROJECT No.: 39826-19 DESIGNED BY:\_ CRA PROJECT NAME: \_\_ CONESTOGA-ROVERS & ASSOCIATES CHECKED BY: 4/11/16 DATE: OF. PAGE \_ Partel garage comple L'At grate Concernie ! 1 Steen 1130 Concrete Gresk Deck 125 5-160411-030,034 3 story pointed 5.5 Gloring & and Concrete / Brich 2 CONNER 20 5100 Portrolate well belod Loomis



A SA COMMON CONTRACTOR AND A		NON-RESPONSIVE
Parcel Landscape Area	A	Current Ad
Lawn Area		Restoration Plan
Flowers/Plants:	☐ Yes ☐ No	
Soil (grade) next to structure:	☐ Yes ☐ No	
Shrubbery:	☐ Yes ☐ No	
Trees:	☐ Yes  ☐ No	
Sidewalks		Restoration Plan
Sidewalk:	☐ Yes   No	5,2000 CONDOO 8000
Tree Roots:	⊠Yes □ No	
Sections Missing:	☐ Yes ⊠No	
Other:	☐ Yes ☐ No Ro	more one foot at soil next to back
Signatures Inspection Form Signatures <u>Be</u>	fore Removal Action	NON-RESPONSIVE
ESPÓNSIVE		
Name of Florite Owner	Signature	Date
17-11 Pale	111	110 4/12/1-
GHD	Signature	Date
Inspection Form Signatures Aft RESPONSIVE	er Removal Action	
RESPONSIVE		
		4-13-2017
Name of Home Owner	Signature	/ Dafe
Walter Pochion	11/2/11/11	4/12/17
CHD	Signatura	Pote



Photo 1 – Before Remediation Back Yard




Photo 2 – Before Remediation Back Yard (2)







Photo 3 - During Remediation Back Yard



Photo 4 – During Remediation Back Yard (2)







Photo 5 - After Remediation Back Yard



Photo 6 – After Remediation Back Yard (2)





#### CONSENT FOR ACCESS TO PROPERTY

NON-RESPONSIVE		
Nan		
Day		
Eve		
Eve		
Ema		
Add		

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq*.

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described about the property des	ve.
Owner Signature:	<b>V</b>
Owner Name (pri	
Owner's Address (if different from the Address listed above):	

PROJECT No.: 39826-19 DESIGNED BY: CRA PROJECT NAME: \_ CONESTOGA-ROVERS & ASSOCIATES CHECKED BY: OUZ DATE: 4/11/16 PAGE . OF S-160411-9w-035 MS/MSD (25 (2)) P 03 M POSEX - 400×10rec (). Concrete 20 8410 125 Nose govern Brick thorio How Carre Consch 12 Park while reading wall be low perfor 25 low local 16.5 رسخان



Photo 1 - Before Remediation Back Yard



Photo 2 – Before Remediation Back Yard (2)







Photo 3 – Before Remediation Back Yard (3)




Photo 4 - After Remediation Back Yard



Site Photograp






Photo 5 – After Remediation Back Yard (2)





#### CONSENT FOR ACCESS TO PROPERTY



I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq*.

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE

		HIR AIR H.S.	4 9 P R 0 9 P R R R R W	
•	NON-RESPONSIVE			
	<u>α</u>			
		 ,		

Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq*.

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of—any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE		
Owner Signature		
Owner Name (p		
Owner's Address (if different from the Address listed	above):	

PROJECT No.: 39826-19 DESIGNED BY: CRA PROJECT NAME: \_\_\_ NONERESPONSIVE IATES CHECKED BY: DATE: char-linkfence Convede woll Florence Porkery Deck 0 Fosibleton wall (3) 0 cham Ink S-160412-9W-046



Photo 1 – Before Construction Lot



Photo 2 – Before Construction Lot (2)



Site Photographs NON-RESPONSIVE



Photo 3 – After Construction Side Yard



Photo 4 – After Construction Front Gardens (2)



Site Photograp





Photo 5 – After Construction Front Gardens



Photo 6 – After Construction Back Yard



## Site Photogra





Photo 7 – After Construction Back Yard (2)








Structure

NON-RESPONSIVE

urrent Address:

Description

Property sampled last year (20016); when there was only a vacant lot.



ſ	ON-RESPONSIVE	
	SA-NESI ONSIVE	
Name		
Daytir		
Eveniı		
Email		
Addre		

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq*.

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE

Ow

Ow




Structure

NON-RESPONSIVE

Current Address:

Description

EXCAVATE AROUND THE TREES AS MUCH AS POSSIBLE WITHOUT OVER-EXPOSING





Parcel Landscape Are	39		Current Addi
Lawn Area	-4		
Flowers/Plants:	□Yes	□ No	Restoration Plan
Soil (grade) next to structure:	☐ Yes	□ No	
Shrubbery:	Yes	□ No	TWO PINES
Trees:	Yes	□ No	TWO PINES
Sidewalks			Restoration Plan
Sidewalk:	☐ Yes	□ No	Nestoration Flat
Tree Roots:	Yes	□No	TWO PINES
Sections Missing:	☐ Yes	□ No	1125
Other:	Yes	□No	UPPER LEVEL WILL GET GRAVEL
Signatures Inspection Form Signatures Be	ofore Removal A	ction	LOWER LEVEL WILL GET DIRT & M
	efore Removal A	or []	1/179//
Inspection Form Signatures Booksive	Signatu	or /	Date 11/29/17



Structure

Current Address:

Description

EXCAVATE AROUND THE TREES AS MUCH AS POSSIBLE WITHOUT OVER-EXPOSING

NON-RESPONSIVE






Photo 1 – Before Remediation Under Driveway



Photo 2 – Before Remediation Under Driveway (2)



Site Photograp





Photo 3 – Before Remediation Back Yard



Photo 4 – During Remediation Back Yard









Photo 5 – After Remediation Under Driveway



Photo 6 – After Remediation Under Driveway (2)







Photo 7 - After Remediation Back Yard






NON-RESPONSIVE CONSENTIMIENTO PARA EL ACCESO A LA PROPIEDAD
Dirección completa de la propiedad.
Doy mi consentimiento a los funcionarios, empleados, contratistas y representantes autorizados de la Agencia de Protección Ambiental de los Estados Unidos (EPA) y / o de H. Kramer & Company (H. Kramer) para que entren y tengan acceso continuo a la propiedad indicada arriba para realizar las siguiente acciones de respuesta:
<ol> <li>Recolección de muestras de la superficie y bajo la superficie incluyendo – pero sin limitarse – a la tierra y al aire;</li> </ol>
<ul> <li>(2) Documentación de las observaciones científicas y de ingeniería incluyendo – pero sin limitarse – a tomar notas, fotografías y estudios topográficos;</li> </ul>
(3) Eliminación de tierra contaminada y actividades relacionadas; (4) Cumplimiento con las medidas de restauración una vez que se haya removido la tierra contaminada incluyendo el suministro de tierra impoluta por la tierra removida, el suministro de césped para las áreas previamente cubiertas de hierba, la restauración limitada del jardín, la sustitución de grava, e reparo de posibles daños o por pérdida de propiedad como resultado directo del muestreo, la remoción, y las actividades de restauración; y
(5) Otras acciones que sean necesarias para proteger la salud humana y el medio ambiente según determine el coordinador de acciones en terreno de la EPA.
Entiendo que estas posibles acciones se llevan a cabo de acuerdo con las autoridades de respuesta según la Ley de Responsabilidad, Compensación y Recuperación Ambiental de 1980, según enmendada, 42 USC Sección 9601et seq.
Yo doy este permiso escrito voluntariamente, en nombre mío y de todos los otros dueños de la propiedad con el conocimiento de mi derecho a revocar mi consentimiento voluntario en cualquier momento, y sin ningún tipo de amenaza o promesa. Entiendo que la EPA, H. Kramer, o sus representantes autorizados se pondrán en contacto conmigo antes del inicio de cualquier investigación o actividad de restauración en mi propiedad, y voy a notificar a todo inquilino en mi propiedad de cualquier investigación o actividad de restauración.
Este documento debe ser firmado únicamente por el propietario legal de la propiedad indicada arriba.
Firma del p
Nombre del
Dirección completa del dueño (si es diferente a la dirección que aparece arriba):

Por favor, firme y devuelva este formulario a: Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604



NON-RESPONSIVE	
Structure	Current Address:
Description	100
SIDE STRIP HAS 20-25 BUSHES	






Photo 1 – Side Strip



Photo 2 – Side Garden







Photo 3 – Back Garden





CONSENT FOR ACCESS TO PROPERTY



I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq*.

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE



NON-R Structure	ESPONSIVE				Current Address:	
Description				<u>.,71</u>	Current Address.	
	) <sub>og</sub>	•	·			
Sketch of Prop	erty			and particular section in the section is a section in the section in the section is a section in the section in the section in the section is a section in the section in t	$\rightarrow \mathcal{N}$	
and the second	1-1	1	<u> </u>		The second secon	
	3,50					
TE ALLEN AND AND AND AND AND AND AND AND AND AN		4		<b>N</b>		
SERVICE STORM CHARLES STORM CH		100	21.50 Le Dus	S. A.	SNO 25/6 W	n of
Wooden in the control of the control	.   A	19 19 19 19 19 19 19 19 19 19 19 19 19 1	140.57	Comer	5120 1904	
	1251 Colleget			10	THE STATE OF	#
			21.5	° LE	100 M	
		Ž.	æ	Barre	0855	Security Control of the Control of t
	3.5	÷.	(gray)	P.		
		Consumer of the Consumer of th	Pra.			
	- <del> </del>	7	5		and the state of t	
- The second distance		$\Lambda$	2 - D			



Lawn Area		Restoration Plan
Flowers/Plants:	☐ Yes XNo	Owner requested small garder
Soil (grade) next to structure:	☐ Yes XNo	to be covered by sod.
Shrubbery:	☐ Yes T⊠No	
Trees:	Yes □ No	One Tree
Sidewalks		Restoration Plan
Sidewalk:	ĭXYes □ No	Plan Excavate front yard
Tree Roots:	¥ Yes □ No	to 1-foot below current grade
Sections Missing:	☐ Yes ☑ No	Place visual barrier, Cover wi+
Other:	☐ Yes ☐ No	1-foot of Jour soil and place
Signatures	ter Berein ten	41.1.
Han Navavro	Signature	4/25/17 Date 4/25/17 Date
NSIVE SIGNATURA PAR		4/25/17 Date 4/25/17 Date
Han Vavavro		



Structure

Current Address:

#### Description

SHUHT DOWN SLUPE WAS LEFT ON SONTH SIDE OF YARD. THIS IS DUE TO NEXT DOUR NEIGHBOR HAVING FLOODING ISSUES. PROPERTY OWNER WAS OK WITH SLUPE.






Photo 1 – Before Remediation Front Yard



Photo 2 – During Remediation Front Yard



# Site Photograph





Photo 3 – During Remediation Front Yard (3)



Photo 4 – During Remediation Front Yard (2)









Photo 5 – After Remediation Front Yard



Photo 6 – After Remediation Front Yard (3)







Photo 7 – After Remediation Front Yard (2)





I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq*.

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE

PROJECT No.: 39826-19 DESIGNED BY: CRA PROJECT NAME: \_ **CONESTOGA-ROVERS & ASSOCIATES** CHECKED BY: OUZ DATE: 415/16 PAGE \_ chan-luk Perce College Aller 5-160405-gw-816 Enpty Lot 6 0 Slepe Particolate really well below octor eAllport >



Photo 1 – Sampling Open Lot





	CONCENT FOR A COFCE TO BRODEDTY
NON-RESPONSIVE	
Na	
Da	
Ev	
En	
Ac	

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq*.

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This docume	nt should be stoned N-RESPONSIVE	t only by the lega	Lowner of the pr	onerty described	above	
Owner Sig						
Owner Na						
Owner's A						




Structure

NON-RESPONSIVE

Current Address:

Description

GARDEN HAS A PINE ON WEST SIDE (TOPTIER). TIER HELD UP BY UNCEMENTED BRICKS.





NON-RESPONSIVE

Lawn Area			Restoration F
Flowers/Plants:	☐ Yes	□No	Hostas beeing remove
Soil (grade) next to structure:	□ Yes	□No	Trostas pecing romere
Shrubbery:	∑ Yes	□No	Small sapling trees removed
Trees:	Yes	□No	Sunfice Soil removed, trees left
Sidewalks			Restoration Plan
Sidewalk:	Yes	□ No	
Tree Roots:	Yes	☐ No	
Sections Missing:	☐ Yes	<b>⊠</b> No	
Other:	☐ Yes	☐ No	Remosesoil to maximum extent Prenchable: Replaced with Clear Placed 25 bag of topsoil from Hom Earth Grow.
			Prenchable: Replaced is the Clear
Name of Home Owner	Signat	ure	Date
	Signat	ure	
GHD			Date
	<u>er</u> Removal Ac		Date
Inspection Form Signatures Aft	ter RemovaJ₋Ac		Date
Inspection Form Signatures Aft	ter RemovaJ.Ac		4/25/17
Inspection Form Signatures Aft	ter RemovaJAc		4/25/17 Date
Inspection Form Signatures Afterponsive	ter Removal Ac	tion	4/25/17



Structure

Current Address:

Description

CARDEN HAS A PINE ON WEST SIDE (TOPTIED). TIER HELD UP BY UNCEMENTED BRICKS.

NON-RESPONSIVE






Photo 1 – Before Remediation Back Garden – Photo Taken by EPA START 05/02/13



Photo 2 – During Remediation Back Garden

## **Site Photograp**







Photo 3 – During Remediation Back Garden (3)



Photo 4 – During Remediation Back Garden (2)









Photo 5 – After Remediation Back Garden



Photo 6 – After Remediation Back Garden (2)



Site Photograph



		CUINSIGNE	BUR AUG	HOSS TO P	ROPERTY	
	NON-RESPONSIVE					
Name						
Daytii						
Eveni						
Email						
Addre						

I consent to officers, employees, contractors, and admortized representatives of the officer states.

Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

Collecting samples, surface and subsurface, including but not limited to soil and air;

(2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying:

Removing contaminated soil and related activities;

(4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and

(5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 et seq.

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.



PROJECT No.: 39826-19 DESIGNED BY: KILLIN CRA PROJECT NAME: \_\_\_ **CONESTOGA-ROVERS & ASSOCIATES** H. KRAMER- OUZ CHECKED BY: 5/12/14 PAGE \_\_1 \_\_ oF\_\_\_\ DATE:\_ Z 6 CENENT CARPIL SXATUS 553 CEMENT Soal SAMPHE 8-160512-62-48 ANG WOLL DELL いっととという 20 COUNTRY x2.5, CEMENT -4 う金てつ CENENT BALL SOTUMBE CAMEL, COLLECT " FRONT BREL



lowers/Plants: oil (grade) next to structure: shrubbery:	☐ Yes		Restoration Plan
		MNO	
shrubbery:	Yes	□No	Excavating under wooden deck-Iftexcau
	☐ Yes	No	replacing with gravel
rees:	☐ Yes	<b>No</b>	
Sidewalks			Restoration Plan
Sidewalk:	☐ Yes	□ No	other sechan not sampled due to grav
Tree Roots:	☐ Yes	No	
Sections Missing:	☐ Yes	No	
Other:	XYes	□ No	Small sections next to driveway - replacing with gravel
PONSIVE			



NON-RESPONSIVE

Structure

Current Address:

### Description

- AREA UNDER DECKISTAIR, IN BETWEEN BUILDINGS WAS EXCAUSE ONF FOOT (WHERE ALLOWED) & BACKFILLED WITH GRAVEL

- SMALL PATCHES IN DACK WERE EXCATED & BACKFILLED WITH GRAVEL

